



HANGER BOLTS



Size	A	B	C	D	
	Standard Length	Machine Thread Length	Lag Thread Length	Center Space	
10-24	x1-1/2	1-1/2	5/8	7/8	—
	x1-3/4	1-3/4	3/4	1	—
	x2	2	1	1	—
	x2-1/2	2-1/2	1	1-1/2	—
	x3	3	1-1/2	1-1/2	—
1/4-20	x1-1/2	1-1/2	1/2	3/4	—
	x1-3/4	1-3/4	3/4	1	—
	x2	2	1	1	—
	x2-1/4	2-1/4	1	1-1/4	—
	x2-1/2	2-1/2	1	1-1/2	—
	x3	3	1-1/2	1-1/2	—
	x3-1/2	3-1/2	1-1/2	2	—
	x4	4	2	2	—
	x4-1/2	4-1/2	1-1/8	3	3/8
	x5	5	1-1/8	3	7/8
	x6	6	1-1/4	3	1-3/4
5/16-18	x1-1/2	1-1/2	5/8	7/8	—
	x1-3/4	1-3/4	3/4	1	—
	x2	2	1	1	—
	x2-1/4	2-1/4	1	1-1/4	—
	x2-1/2	2-1/2	1	1-1/2	—
	x2-3/4	2-3/4	1-1/4	1-1/2	—
	x3	3	1-1/2	1-1/2	—
	x3-1/2	3-1/2	1-1/2	2	—
	x4	4	2	2	—
	x4-1/2	4-1/2	1-1/8	2	7/8
	x5	5	1-1/8	3	7/8
x5-1/2	5-1/2	1-1/8	3	1-3/8	
x6	6	1-1/4	3	1-3/4	
3/8-16	x2	2	1	1	—
	x2-1/2	2-1/2	1	1-1/2	—
	x3	3	1-1/2	1-1/2	—
	x3-1/2	3-1/2	1-1/2	2	—
	x4	4	2	2	—
	x4-1/2	4-1/2	1-1/8	3	3/8
	x5	5	1-1/8	3	3/8
	x5-1/2	5-1/2	1-1/8	3	1-3/8
	x6	6	1-1/4	3	1-3/8
	x8	8	2-1/2	3	2-1/2
x10	10	2-1/2	3	4-1/2	